
HAMMOND REEF GOLD PROJECT RESPONSE TO COMMENTS ON FINAL EIS/EA

COMMENT – T-3

Source: Canadian Environmental Assessment Agency

Summary of Comment

On Figure 4-9, a fourth option for the tailings management facility is shown, however it appears that this should be WRMF 4.

Proposed Action

Confirm that the feature in Figure 4-9 is a waste rock stockpile alternative and not a tailings alternative.

Reference to EIS

EIS Figure 4-9, page 4-65

Response

In Figure 4-9, the feature identified in the legend as Alternative 4 under the Tailings Management Facility heading is a Waste Rock alternative and should be under the Waste Rock Management Facility heading.