Version 3 Hammond Reef Gold Project EIS/EA – Addendum (Part B) Responses to Provincial Information Requests

1656263

Identifier	Торіс	Reference to EIS/EA Report	Summary of Comment	Proponent's Response	Subsequent Comment
			Date: March 2014	Date: June 2015	
MOE SW-4	Water Quality/ Seepage		Additional details and clarification must be provided regarding the potential impacts to Lizard Lake due to seepage losses from the Tailings Management Facility and the associated water management facility (i.e.: perimeter ditches).	On April 28, 2014 Canadian Malartic Corporation hosted a water quality workshop with the Government Review Team. We also initiated communications with the Regional Groundwater Group Leader for MOE's Northern Region who stated on May 15, 2014 that upon further clarification he is "satisfied at this time with the estimates of seepage to Lizard Lake." Please also see response to <u>MOE GW-1</u> , which identifies additional modelling completed and confirms Canadian Malartic's commitment to adjust the detailed design, and monitoring based on additional data collected at the detailed design phase, and ongoing discussions with the regulators during the permitting phase. Further details of this modelling evaluation are provided in the memorandum entitled <i>'Tailings</i> <i>Management Facility, 3D Groundwater Modelling'</i> provided <i>in</i> <i>Part D of the Addendum to the Version 3 EIS/EA.</i> as a <u>supplemental to the Final EIS/EA Report</u> .	MOE SW-4B