Version 3 Hammond Reef Gold Project EIS/EA – Addendum (Part B) Responses to Provincial Information Requests

1656263

ldentifier T	Торіс	Reference to EIS/EA Report	Summary of Comment	Proponent's Response	Subsequent Comment
			Date: March 2014	Date: June 2015	
	Vater Quality		The TSD indicates that Premier Lake was sampled but there is no sampling location in Premier Lake indicated on Figure 2-1 or on the updated map provided in the Appendix 1.IV of the February 2013 submission. There is a sampling location (HRWQ28) indicated on the maps between Lumby Lake and Herontrack Lake along the Premier Road. Sampling locations must be verified.	As noted in Section 2.2.1 of the Water and Sediment Quality TSD, the water quality sampling program was modified March of 2012 to address changes to the location of Project components. This modification included the removal of some existing and the addition of new surface water/sediment stations. Among the stations removed were water column profile sampling locations on Light Bay (HRWQP-4) and Premier Lake (HRWQP-8). Figure 2-1 of the Water and Sediment Quality TSD shows the active stations following this modification. The Premier Lake sampling location (HRWQP-8) is provided in Table 2-1 of the Water and Sediment Quality TSD and the results from the 2010 and 2011 monitoring programs are provided in Appendix 2.III of the Water and Sediment Quality TSD.	MOE SW-9B